

1906 Brig Daisy bound to New Bedford
 Saturday May 12^a
 this day comes in with light
 breeze from E. S. E. Steaming
 N. W. by N. employed painting
 ships in side do on
 fat 26-17
 fong 59-08

Sunday May 13^a
 this day comes in with strong
 breeze land squalls wind N. E.
 part and middle part later
 part E Steaming N. W. by N. 1/2 N
 took in gaff top sail rail
 jib top still do on
 fat 24-27
 fong 60-30

Monday May 14^a
 this day comes in with light
 breeze from E Steaming N. W.
 by N. lowered painting in
 wide one sail in slight
 going to Northward do on
 fat 29-07
 fong 63-11

1906 Brig Daisy bound to New Bedford
 Tuesday May 15^a
 this day comes in with light
 wind first part E to N E middle
 part N. E Steaming N. W. by N
 in N. all sail set do on

fat 30-46
 fong 64-45

Wednesday May 16^a
 this day comes in with light breeze
 part of time wind S. E. Steaming
 N. W. by N. 1/2 N employed in green-
 ing don't spare and varnishing the
 fore mast do on

fat 31-46
 fong 65-48

Thursday May 17^a
 this day comes in with light breeze
 from S. S. E. Steaming N. W. by N. 1/2 N
 set main sail and gaff top sail
 and head sails do on

Friday May 18^a
 this day comes in with light
 breeze the first part middle and
 later part good breeze from S
 with main shaker Steaming
 N. N. W. do on

fat 33-47
 fong 65-05 at 8 a.m.