

Remarks on Board Brig Trabella 1878

Tuesday May 21st

fresh breeze from the S.E. with rain squalls bore by the wind heading S.E. employed fitting Boats for Whaling

Lat 31.20 N Long 123.50 W

Wednesday May 22nd

light breeze from the S.E. with calm weather Breeze heading to the Eastward

Thursday May 23rd

fresh breeze from the S.W. Steering S by N Saw one sail

Lat 28.20 N Long 125.30 W

Friday May 24th

Strong breeze from the S. with rain squalls Steering S by N

Saturday May 25th

Strong breeze from S. to S.E. with rain and fog Brig Steering from E by N to N.E. by E Saw one sail

Sunday May 26th

moderate breeze from the S.E. with clear weather Brig S.E. Saw five boats and one sail

Lat 49.12 Long 78.36 W

Monday May 27th

light breeze from the S. with fog and rain Steering S.E.

Lat 44.52 N Long 78.11 W

Capt George Irvine Master

Tuesday May 21st

moderate breeze from the W. Steering N.E. foggy weather Saw two sails took the Boat off the Stern and put it on the Starboard Grains port Lumber over the Stern

Lat 46.33

Wednesday May 22nd

Strong breeze from the S.W. with rain Steering S by E

Lat 49.07 N

Thursday May 23rd

fresh breeze from the S.E. with rain and fog Brig by the wind heading S by E Saw a Steamer heading to the Westward

Lat 50.14 N Long 70.53 W

Friday May 24th

fresh breeze from S. to S.E. Brig by the wind to the S. thick rainy weather

Lat 50.50 N

Saturday June 1st

fresh gale from the S.W. with thick weather Brig lying to on the eastern tack S.B. got hold in her Bow by coming in contact with the cutting stage a sea floated one iron out of the S.B. at 10 P.M. broke jib Boom off by the cap fore topgallant mast jib and flying jib stays one Back rope jib ropes flying jib gear destroyed jib and flying jib by Parting and a sea striking the Boom at the same time

Lat 51.12 N