

Wed Oct 13th

This day began with light S.W. wind
all sail out steering S.E. later part
strong S.W. and rain 3 masted Schooner
in sight at 7 P.M. reef trysails
becoming heavy gale at 11 P.M.
lost S.B. and W.B. sea threw
the Starboard Anchor on the deck
stove the fore sail door stove the hull
works the vessel sprung leaking
no Obs.

Thurs Oct 14th

This day began with strong N.W. gale
still under reef main trysail
later part moderate steering S.S.E.
Lat 35-40
Lon 58-40

Fri Oct 15th

This day began with light S.S.E. wind
steering by the wind heading S. by E.
repaired the Head gear
Lat 35-38
Lon 58-43

Sat Oct 16th

This day began with strong S.W. wind
steering S.E. by E. saw a ship bound
to North
Lat 35-41
Lon 58-24

Sun Oct 17th

This day began with strong S.W. wind
steering S.E. later part light S.W.
Lat 35-28
Lon 57-50

Mon Oct 18th

This day began with light N.W. wind steering
S.E.
Lat 34-40
Lon 50-05

Tues Oct 19th

This day began with light Easterly wind over
cast light rain
Lat 34-00
Lon 48-41

Wed Oct 20th

This day began with strong S.W. wind
rain thunder lightning all day at day light
raised a lone whale going quick seen one
riser seen a steamer bound East no Obs

Thurs Oct 21th

This day began with strong southerly wind
squally rain all day steering S.E.
Lat 33-00
Lon 46-00

Fri Oct 22th

This day began with strong S.S.W. wind
rain all day steering S.E. no Obs.

Sat Oct 23th

This day began with strong S.S.E. wind
steering by the wind
Lat 32-55
Lon 42-37

Sun Oct 24th

This day began with light S.E. wind
later part calm seen tow. steamers bound
to the Eastward
Lat 33-08
Lon 40-14